



Weld Aid Weld-Kleen 350






INGREDIENTS	CAS NO	%	TWA
oleic acid	112-80-1	1-3	-
water	7732-18-5	>90	-

GHS	DG
Not Applicable	UN No: Not Applicable Hazchem Code: Not Applicable DG Class: Not Applicable Subsidiary Hazard: Not Applicable Packing Group: Not Applicable








PROPERTIES
  Liquid. Mixes with water. Non-combustible.

HEALTH HAZARD INFORMATION
Determined by Chemwatch using GHS/HSNO criteria Gazetted by EPA New Zealand Signal word: Hazard statement(s): Not Available

EMERGENCY
    

PRECAUTIONS FOR USE
    
Appropriate engineering controls: General Exhaust Ventilation adequate.
Glasses: Consider chemical goggles.
Gloves: 1.NEOPRENE 2.NATURAL+NEOPRENE
Respirator: Type A-P Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)
Storage and Transportation: Store in cool, dry, protected area.

FIRST AID
Swallowed: Rinse mouth with water.
Eye: Wash with running water. For discomfort seek medical advice.
Skin: Remove contaminated clothing. Wash with soap & water.
Inhaled: Fresh air. Rest, keep warm.
Advice To Doctor: Treat symptomatically.
Fire Fighting: Keep surrounding area cool. Water spray/fog.
Spills and Disposal: Absorb with dry agent. Stop leak if safe to do so.

SAFE STORAGE WITH OTHER CLASSIFIED CHEMICALS
      
+ + + + + + +
x — Must not be stored together 0 — May be stored together with specific preventions + — May be stored together

Note: Depending on other risk factors, compatibility assessment based on the table above may not be relevant to storage situations, particularly where large volumes of dangerous goods are stored and handled. Reference should be made to the Safety Data Sheets for each substance or article and risks assessed accordingly.